






S50





PE88.79-P-2000-60MA	Legend, wiring diagram of outside mirrors	
---------------------	---	--

Code	Designation	Coordinate
F1	Fuse box	8L 17L
F1f2	Fuse 2	17K
F1f26	Fuse 26	7K
K13/4	Heated windshield relay	12K
M21/1	Left electrically adjustable and heated outside mirror	4L
M21/2	Right electrically adjustable and heated outside mirror	20L
N72	Lower control panel control module	14K
S50	Outside mirror adjustment switch	2A 12A 22A
S63	Heated windshield switch	10K
W29/1	Left A-pillar ground	6L
W41	Center console E-box ground	23L
W64	Left rear center console ground	9L
X141/2	Mirror/CL [ZV] intermediate connector	1G
X141/3	Mirror/CL [ZV] intermediate connector	18G
X29/13	Center console connector 1	1E
X29/9	Center console connector 2	19E
Z117/2	Heated windshield/mirror connector sleeve	10E
Z29/6	Circuit 58 connector sleeve	15E